



















ENGINEERING CHANGE NOTICE

Northern Technologies <u>CLASS</u> <input checked="" type="checkbox"/> NEXT BUY <input type="checkbox"/> NEXT PRODUCTION <input type="checkbox"/> WORK IN PROCESS <input checked="" type="checkbox"/> FINISHED GOODS <input type="checkbox"/> RETURNS FROM FIELD <input type="checkbox"/> UNITS IN FIELD <input checked="" type="checkbox"/> UNITS IN STOCKROOM	<u>ORIGINATOR</u> J. DiPietro	<u>DATE</u> 27-FEB-14	<u>ECN</u> 0737								
	<u>PRODUCT TO BE CHANGED</u> DE Series Connectors		<u>EFFECTIVE DATE</u> 27-FEB-14								
	<u>P/N</u> (X) DEXXXXXX										
<u>TYPE OF CHANGE</u> <input type="checkbox"/> DOCUMENTATION ONLY <input checked="" type="checkbox"/> Part Number	<u>REASON FOR CHANGE</u> Update Part Numbering System to avoid error in product material & finish.										
<u>REASON FOR CHANGE</u> <input type="checkbox"/> DRAWING ERROR <input type="checkbox"/> FACILITATE MFG <input type="checkbox"/> MEET SPECS <input checked="" type="checkbox"/> PRODUCT IMPROVEMENT <input type="checkbox"/> VENDOR <input type="checkbox"/> _____	<u>DESCRIPTION OF CHANGE</u> Dwg. # 0002-200-155 Rev. E 1. In ORDER INFORMATION section change from EMPTY: MACHINED CONTACTS to M: MACHINED CONTACTS 2. Add Rev. F 3. Transfer existing stock per SYSPRO 6.1 to new part numbers. Reference old part number description to new part number.										
<u>DOCUMENTS REVISED</u> <input checked="" type="checkbox"/> ASSEMBLY DRAWING <input checked="" type="checkbox"/> BILL OF MATERIALS <input checked="" type="checkbox"/> QA PROCEDURE <input type="checkbox"/> SCHEMATIC <input checked="" type="checkbox"/> FABRICATION DWG <input type="checkbox"/> TEST PROCEDURES <input type="checkbox"/> SYSPRO _____	<table border="1"> <tr> <td> <u>ENGINEERING</u>  </td> <td> <u>MATERIALS</u>  </td> </tr> <tr> <td> <u>PRODUCTION</u>  </td> <td> <u>PRODUCT MKTG</u>  </td> </tr> <tr> <td> <u>QUALITY ASSURANCE</u>  </td> <td> <u>TEST ENGINEERING</u>  </td> </tr> <tr> <td> <u>VICE PRESIDENT</u> </td> <td> <u>DESIGN</u> </td> </tr> </table>			<u>ENGINEERING</u> 	<u>MATERIALS</u> 	<u>PRODUCTION</u> 	<u>PRODUCT MKTG</u> 	<u>QUALITY ASSURANCE</u> 	<u>TEST ENGINEERING</u> 	<u>VICE PRESIDENT</u>	<u>DESIGN</u>
<u>ENGINEERING</u> 	<u>MATERIALS</u> 										
<u>PRODUCTION</u> 	<u>PRODUCT MKTG</u> 										
<u>QUALITY ASSURANCE</u> 	<u>TEST ENGINEERING</u> 										
<u>VICE PRESIDENT</u>	<u>DESIGN</u>										
<u>ENCLOSURES</u>											
<u>COSTS</u> TIME: HRS @ _____ = _____ MATERIALS _____ = _____ TOTAL= _____											